






FIG. 1 FIG. 2















FIG. 8



11	1	1112
Scaffold Information System	Trade Supervision Task Sign-Off Ironworkers: Pipefitters: Boilermakers: Electricians: Pipe Inspection: Heat Tracing: Insulation: Test: Tear Down:	
110	FIC 10A	

fte	Name:
Pipefitt	Location: Foreman: Signature:
	Day Shift: Night Shift: Safety Dept. / Loss Management DO NOT REMOVE

120

FIG. 10B




FIG. 11

